

Critical success factors

- Water flow, speed of water
- Debris and cleaning, risk of damages
- Turbulence and water suction
- Distance between scanner plates
- Position of scanner in the waterfall
- Protection from vandalism
- Telephone contact at site
- Cables and connections, silicon compound
- Easy removal of equipment
- Design of the in-scale, width between bars
- Easy way out for the fish
- Good people at site for inspection and cleaning