


Connecting DU to PC




Connect the Display Unit to the PC with the data cable supplied with the system. The 9 pin connector plugs into COMport 1 on the computer (default setting).

Downloading data



Erasing data

After securely downloading the data, then reset the DU and frame, by pressing the RESET button on the DU when connected to the frame. Press ENTER to confirm.



Vaki Biomass Counter quick guide

Display Unit Functions (Vers. A:8.08)

Vaki Aquaculture Systems Ltd.
Akralind 4, 201 Kópavogur, Iceland
Phone: +354 595 3000 Fax: +354 595 3001
www.vaki.is